

Quick ▶▶▶▶▶ installation guide

Start here first ▶

56K V.92 PCI Modem

HM92P



Website: www.hawkingtech.com
E-Mail: techsupport@hawkingtech.com


© Copyright Hawking Technologies, Inc. All rights reserved.

rev. C2



Installation Steps

1. Turn off the system and unplug your system from the power supply.
2. Remove the computer cover.
3. Inserting the modem in PCI slot.



4. Connect the phone line to the jack, that indicates "Line", at the end of the modem.
5. Connect another phone line to the other jack that labels "Phone", at the end of the modem.
6. Turn your computer on.



Driver Installation

56K V.92 PCI Modem

Windows ME

1. Boot the system. The system will detect the new HM92P device and request you to install its driver.
2. Choose "Specify the location of the driver". Click the [Next] button.

Automatic search for a better driver (Recommended)

Specify the location of the driver (Advanced)

3. Choose "Specify a location".
4. Insert the driver CD into the CD-ROM drive . Click [Browse] and choose the CD-ROM Location (Ex: E:\Driver\WinME).

Search for the best driver for your device. (Recommended).

Removable Media (Floppy, CD-ROM...)

Specify a location:

[v] [Browse]

Display a list of all the drivers in a specific location, so you can select the driver you want.

5. Click the [Finish] button. Repeat step 2, step 3, step 4, and step 5, once again.
6. Windows ME will copy the file into your hard disk. Click the [Finish] button.




Driver Installation

56K V.92 PCI Modem

Windows 2000

1. Boot the system. The system will detect the new HM92P device and request you to install its driver. Click the **[Next]** button.
2. In the new dialog box, you have two driver installation options. The default choice is “Search for a suitable driver for my device”. Click the **[Next]** button to continue.



3. Choose “Specify a location”. Click the **[Next]** button.



4. Insert the driver CD into the CD-ROM device. Click Browse and choose the CD-ROM Location (Ex: E:\Driver\Win2000).
5. Windows 2000 will copy the file into your hard disk. Click the **[Finish]** button.




Driver Installation

56K V.92 PCI Modem

Windows XP

1. Boot the system. The system will detect the new HM92P and request you to install its driver.
2. Boot the system. The system will detect the new
3. Driver Update Choose Control Panel → System → Hardware → Device Manager → Generic SoftK56 → Update Driver




4. Select: Install from a list or specific location
→ Next → Don't search. I will choose the driver to install → Next → Choose Have Disk for driver folder → Next.



Driver Installation

56K V.92 PCI Modem



5. Windows XP will copy the file into your hard disk. Click the **[Finish]** button.

